

FIG. 1B





FIG. 1A



FIGS. 2A-2B

FIG. 3A




FIG. 3D






FIG. 3B

FIG. 3C






FIG. 4A






FIG. 4B






FIG. 6A




FIG. 6B




FIG. 6C




FIG. 6D




FIG. 8A




FIG. 8B





FIG. 8C



FIG. 8D







FIG. 10A



1010

EXPOSED
BLADE

FIG. 10B





FIG. 10C

RETREATING BEARING BLOCK


FIG. 10D

FIG. 11A




POINTS


FIG. 11B



PETALS



SERRATED



SHARK FINS

FIG. 11C

FIG. 11D

FIG. 12A




FIG. 12B





FIG. 12C






FIG. 13A




FIG. 13B




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18

FIG. 19A




FIG. 19B




FIG. 19C




FIG. 19D




FIG. 20